OUT 65785

23 Aug 68 20

GY

347

DISTRIBUTION OFFICE

CABLE SEC.

TSSU /THO

FPi.3/RD SECUR. 25X1

PSG/00

RRD REPRO

AID LNG

PROD

SCIEN

WEST

MAST M&S

FILE

P 232019Z AUG 68 FM NPIC WASHDC TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB RUCLFGA/100TH SRW OL 19 MCCOY AFB FLA RUWJDBA/100TH SRW DAVIS MONTHAN AFE ARIZ RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD RUEAIIA/CIA WASH DC RUEOJFA/DIA ATTN: DIAXX-2 RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF RUEFHQA/HQS USAF BT

SECRET CITE NPIC 4433.

SAC FOR DIR, DOSR, DISD; 15TH AF FOR DI, DO; 100TH SRW FOR CO, DCOI; HQ USAF FOR AFRDR

FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

SUBJ: EVALUATION OF GLASS LAMP MISSION G-039 1. QUALITY SUMMARY: THIS MISSION PROVIDES POORER IMAGE QUALITY THAN PREVIOUS MISSIONS EMPLOYING UNIT B-24. THE IMAGERY APPEARS SOFT DUE TO EITHER VEHICLE VIBRATION AND/OR POOR FOCUS. THE GROUND RESOLUTION AND INTERPRETATION SUITABILITY ARE POOR DUE TO THIS ANOMALY. CLOUD COVER AND HAZE OBSCURE APPROXIMATELY 15 PERCENT OF THE ENTIRE MISSION.

2. MISSION DATA

A. THE STANDARD "B" CONFIGURATION CAMERA UNIT NUMBER 24 WAS USED IN MISSION G-039 FLOWN ON 21 AUGUST 1968. THIS WAS AN OPERATIONAL MISSION USING THE U-2 AIRCRAFT. MODE V WAS USED THROUGHOUT THE MISSION.

B. FILM TYPE 3400 WAS USED THROUGHOUT THE MISSION. PROCESSINGERM WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN. ALL MATERIAL WAS PROCESSED TO A GAMMA OF Ø.6 AND A SPEED OF 2.32 (LOG E).

3. ORIGINAL NEGATIVE

A. EXPOSURE: THE EXPOSURE IS ADEQUATE WITH SOME INSTANCES UNDEREXPOSURE AT THE BEGINNING OF THE MISSION.

B. DENSITY AND CONTRAST: GENERALLY MEDIUM, HOWEVER, THE FIRST PART OF THE MISSION IS THIN DUE TO UNDEREXPÓSURE.

C. IMAGED DEGRADATIONS

1. BOTH SIDES: OUTBOARD EDGE FOG AND INBOARD ROLLER

CHATTER ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION.

D. PHYSICAL DEGRADATIONS

1. 9R SIDE: A MANUFACTURING SPLICE IS PRESENT BETWEEN

FRAMES 765 AND 766. THERE IS A HEAT SPLICE IN FRAME 480. 2. 9L SIDE: HEAT SPLICES ARE LOCATED IN FRAME 477 AND

BETWEEN FRAMES 599 AND 600. A MANUFACTURING SPLICE IS PRESENT IN

E. AUXILIARY DATA: THE FRAME COUNTER SKIPPED NUMBER 2 AND 1146. ALL OTHER DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY. F. OTHER: THE LAST TITLED FRAME IS 1145, A BIAS OF TWO FROM

THE EVENTS COUNTER.

4. POSITIVES A. THE PRINTING AND PROCESSING WERE GOOD.

GP-1 SECRET

END OF MESSAGE

DIA-XXA SPAD DIAMIP 25X1

TAS

CHA

advance ov CAMITIM? WITH THEF

DROUP 1 Excluded from automatic downstrading and

